

**ALL TYPE OF
MACHINERY
LABELS**



Sahas
Name Plate

MANUFACTURER OF :

- » Aluminium Labels
- » Brass Labels
- » S.S. Labels
- » Poly Carbonate Stickers
- » Dome Stickers
- » Radium Stickers
- » Vinyl Stickers
- » All TYPE Machinery Labels & Stickers

Sahas
Name Plate

PRODUCT _____

MODEL _____

SIZE (m) _____

SERIAL NUMBER _____ WEIGHT (kg) _____

MAX. PTO POWER (KW / H.P.) _____ PTO SPEED (rpm) _____

YEAR OF MANUFACTURE _____

Sahas
Name Plate

| | | |
|-----------------|---------------|----------|
| H.P. 1/15 | VOLTS 220/230 | AMPS 0.6 |
| R.P.M. 3000 | WATT - 50 | |
| MFG. DATE _____ | /201 _____ | |

VATVA, A'BAD

DANGER!

ELECTRIC **440/460** PRESSURE **VOLTS**

खतरा बिजलीका दबाव ४४०/४६० वोल्ट



 **DANGER**

HIGH VOLTAGE



KEEP AWAY

WARNING

OFF

ON

ON OFF

LOW HIGH

BUSBAR ALLEY










Sahas
Name Plate

QC PASSED


Supplier : _____ Qty. : _____

Authorised Sign. _____





ALL TYPE MACHINERY LABELS



DANGER
6000 VOLT
खतरा
६००० वोल्ट

Sahas
Name Plate

A B C

Sahas
Name Plate

Sahas
Name Plate

ON OFF FWD REV

EMERGENCY STOP MOTOR FEED CLAMP/DECLAMP

COUNTER

AUTOMANUAL CYCLE START MOTOR ON MOTOR INDICATOR

Sahas
Name Plate

Sahas
Name Plate












CLIENT. _____
P.O. NO. _____
CONSULTANT _____
NAME OF EQUIPMENT. _____
EQUIP. NO. _____ MFG. DATE _____


| | SHELL | COIL/JKT/TUBES. |
|----------------------------------|-------|-----------------|
| MFG. OF CONST. | | |
| DESIGN PR. KG/CM G ² | | |
| TEST PR. KG/CM G ² | | |
| WORKING PR. KG/CM G ² | | |
| DESIGN TEMP. C ^o | | |
| CAPACITY | | |
| DRG. NO. | | |
| FAB. CODE | | |
| INSP. BY. | | |

1450
1150 1750
850 2050
550 2350
250 2650
rpm 0 2800

SAHAS NAME PLATE

P
U
S
H





WARNING

Hazardous voltage will cause severe injury or death.



Turn off power before servicing



WARNING

Running Hazard

Do not operate before shutting door.




Sahas
Name & Plate

QC PASSED

Supplier: _____ Qty: _____




Authorised Sign: _____





DANGER




MOVING BLADE CAN CAUSE INJURY OPERATE CAREFULLY

| | |
|---|---|
|  | WARNING Never try to contact a running spindle and workpiece in any way. It will cause severe injury. |
|  | TOOL - HOLDER 1. Use high speed tool-holder on this machine. 2. When spindle speed over 8000rpm, must use G2.5(or better)dynamically balanced tool-holder. |
|  | TOOL CHANGE PUSH BUTTON Tool Holder must be Securely hold by hand before depress this button otherwise Tool will fall down and will cause injury. |




DANGER



SAHAS NAME PLATE
SR. NO. :
DATE :





Sahas Name Plate

Add :

**B/34, Siddhpura Estate, Phase - 4,
Vatva, G.I.D.C. Opp. Windsor Machinery,
B/h, Hanuman Temple, Vatva,
Ahmedabad - 382445.**

**E-mail : hk_design2011@yahoo.com
mahendrapchavda@gmail.com**

Web. : www.sahasnameplate.com

MAKE IN INDIA

Contact No. :

98287 32970, 98243 50535

98242 50170, 84600 50170